

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Inspection Report

Supervisor LK

Minerals Regulatory Program
Date of Report: June 10, 2008

Operator Name: Quality Building Stone	Inspection Date: May 12, 2008 Time: 3:30-4:30 PM Weather: Cloudy, 30s, showers, very windy		
Inspector(s): Paul Baker Other Participants: None Mine Status: Active			
Elements of Inspection	Evaluated	Comment	Enforcement
 Permits, Revisions, Transfer, Bonds Public Safety (shafts, adits, trash, signs, highwalls) Protection of Drainages / Erosion Control Deleterious Material Roads (maintenance, surfacing, dust control, safety) Concurrent Reclamation 			
 7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes) 8. Water Impoundments 9. Soils 10. Revegetation 			
11. Air Quality12. Other			

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

1. Permits, Revisions, Transfer, Bonds

The Division holds a surety in the amount of \$22,000.00. It is in the form of a letter of credit issued by Far West Bank, and it is due to be re-evaluated in January 2009.

6. Concurrent Reclamation

This mine site was originally determined to be larger than five acres, but the operator consolidated and removed much of the equipment and materials in an attempt to reduce the size. It does not appear these areas from which items were removed are being used, but there is little or no vegetation in them.

12. Other

I used a GPS unit to measure the size of the quarry itself not including any loading areas or the waste dump outslopes. I obtained a value of 4.45 acres which is comparable to the quarry area of 4.6 acres shown in the

Page 2 of 2

Inspection Date: May 12, 2008; Report Date: June 10, 2008

S0550021

notice of intention. The quarry has been expanded to the northwest which I had feared would make it larger than five acres.

I did not try to measure the size of loading areas, but they appeared to be in the range of about one-half acre.

Conclusions and Recommendations:

The operator should try (or re-try) to establish vegetation in the areas that were formerly used to store and load rocks.

Inspector's Signature

2 13 Ml Date: 6/11/08

PBB:pb

cc: Velina Hansen, Quality Building Stone

 $O: \label{local-wayne} O: \label{local-wayn$



Photo 1. This is the main quarry area.



Photo 2. The east side of the main quarry.



Photo 3. An area formerly used to store and load rocks.



Photo 4. This shows part of the area now being used for storage and loading.